

Run Capacitor Accessories



36-12204
Illustrated

Part #	Description
36-12204	5.16cm x 3.15cm (2.03" x 1.24") Bracket
36-12205	7.11cm x 4.49cm (2.80" x 1.77") Bracket
36-12206	2.75" x 1.44"



36-12211
Illustrated

Protective Rubber Caps

Part #	Description
36-12210	1 Hole Boot
36-12211	2 Hole Boot
36-12211T	2 Hole Boot - Top
36-12212	3 Hole Boot



36-11205
Illustrated

Wire Leads

Part #	Description
35-11205	15.24cm (6") Wire leads c/w push-on terminals. (10/pk)



35-11206
Illustrated

Start Capacitor Accessories

Mounting Brackets

Part #	Description
35-11206	6.9cm (2.75") Bracket
35-11207	8.6cm (3.38") Bracket
35-11208	11.1cm (4.38") Bracket



35-11211
Illustrated

Protective Plastic End Caps

- On motor end cap leads through bracket.

Part #	Description
35-11210	3.6cm (1 7/16")
35-11211	4.6cm (1 13/16")
35-11212	5.0cm (2 1/16")
35-11213	6.5cm (2 9/16")



35-11216
Illustrated

Protective Plastic End Caps

- On motor end cap top side leads.

Part #	Description
35-11215	3.6cm (1 7/16")
35-11216	4.6cm (1 13/16")
35-11217	5.0cm (2 1/16")
35-11218	6.5cm (2 9/16")



36-11204
Illustrated

Push-On Adaptors

Part #	Description
35-11204	Converts spade terminals to screw. (25/pk)



35-11205
Illustrated

Wire Leads

Part #	Description
35-11205	15.24cm (6") Wire leads c/w push-on terminals. (10/pk)



35-11201
Illustrated

Bleed Resistor

Part #	Description
35-11201	2 Watt, 15,000 OHM, c/w push-on terminals. (10/pk)



35-11204
Illustrated

Push-On Adaptors

Part #	Description
35-11204	Converts spade terminals to screw. (25/pk)



Your Single Source For Quality Motors, Components & Parts